



Navigation

[Main Page](#)
[All pages](#)
[All categories](#)
[Popular pages](#)
[Popular authors](#)
[Popular categories](#)
[Category stats](#)
[Recent changes](#)
[Random page](#)
[Help](#)
[Google Search](#)

Print/export

[Create a book](#)
[Download as PDF](#)
[Printable version](#)

Toolbox

[What links here](#)
[Related changes](#)
[Special pages](#)
[Permanent link](#)
[Browse properties](#)

Page [Discussion](#) [ce](#) [View history](#)

AM335x-PSP 04.06.00.08 Release Notes

AM335x-PSP

04.06.00.08

Release Notes

Translate this page to [cs](#) - [Česky](#)

Google™ Custom Search



AM335x-PSP 04.06.00.08 Release Notes

Linux PSP

Contents [\[hide\]](#)

- 1 AM335x PSP 04.06.00.08
 - 1.1 Introduction
 - 1.2 Obtaining the Release Package
 - 1.3 Dependencies
 - 1.4 Documentation
 - 1.5 What's Supported
 - 1.6 New in this Release
 - 1.7 Fixed in this Release
 - 1.7.1 ALSA
 - 1.7.2 Base Port
 - 1.7.3 Ethernet
 - 1.7.4 MMC/SD
 - 1.7.5 Power Management
 - 1.7.6 U-Boot
 - 1.7.7 USB
 - 1.8 Known Issues
 - 1.8.1 Audio
 - 1.8.2 Base Port
 - 1.8.3 Ethernet
 - 1.8.4 I2C
 - 1.8.5 MMC/SD
 - 1.8.6 NAND
 - 1.8.7 On-board Components
 - 1.8.8 Power Management
 - 1.8.9 SPI
 - 1.8.10 UART
 - 1.8.11 USB
 - 1.9 Installation and Usage
 - 1.10 Upgrade and Compatibility Information
 - 1.11 Technical Support and Product Updates

AM335x PSP 04.06.00.08

Release Notes

Release Date: August 1, 2012

Introduction

This is Release 04.06.00.08 of [AM335x](#) [Linux PSP](#). This release supports:

- [BeagleBoard Bone](#) [\(version A3 and above\)](#)
- [AM335x Evaluation Module](#) [\(version 1.1A and above\)](#)
- [AM335x Evaluation Module-StarterKit](#) [\(version 1.2B and above\)](#)

The Linux PSP serves to provide a fundamental software platform for development, deployment and execution of Linux based applications on Texas Instruments silicon.

The Linux kernel and U-Boot software in this release are based on the following open source repositories:

| Component | Version | Base Repository | Base Tag (or commit id) |
|--------------|---------|---|--|
| Linux Kernel | v3.2 | http://git.kernel.org/?p=linux/kernel/git/tmlind/linux- | 6489f6de3a219dfd23a91261eea1b09fba7ae128 |

| | | | |
|--------|---------|---|----------|
| | | omap.git;a=summary | |
| U-Boot | 2011.09 | http://git.denx.de/?p=u-boot.git;a=summary | v2011.09 |

The code base for Linux kernel, U-Boot and power management firmware included in this release is hosted at the following repositories:

| Component | Repository & Branch | Release Tag |
|---------------------------|--|---------------------------------------|
| Linux Kernel | http://arago-project.org/git/projects/?p=linux-am33x.git;a=shortlog;h=refs/heads/AM335XPSP_04.06.00.08 (The kernel obtained directly from the above repository needs PM firmware to build when building using default configuration. Link to PM firmware repository containing the firmware binary is available below in this table. Copy the firmware binary .bin file into the firmware/ folder of the kernel sources) | v3.2_AM335xPSP_04.06.00.08 |
| U-Boot | http://arago-project.org/git/projects/?p=u-boot-am33x.git;a=shortlog;h=refs/heads/AM335XPSP_04.06.00.08 | v2011.09_AM335xPSP_04.06.00.08 |
| Power Management Firmware | http://arago-project.org/git/projects/?p=am33x-cm3.git;a=shortlog;h=refs/heads/AM335XPSP_04.06.00.08 | AM335xPSP_04.06.00.08 |

Obtaining the Release Package

The PSP release package can be obtained from TI's [Technology and Software Publicly Available \(TSPA\) download site](#).

Dependencies

| Tool/Component | Description | Release Version | Required for |
|--|------------------------|---------------------|---|
| Code Composer Studio (CCS) | IDE and ARM compiler | 5.1.0.09000 | Building CCS based flash writers |
| Arago Toolchain | GCC ARM cross compiler | 2011.09 (GCC 4.5.3) | Building Linux kernel, U-Boot, Linux examples |
| Filesystem | Target filesystem | NA | Linux boot |

Documentation

The [User's Guide](#) provides instructions on how to use the PSP Release package.

The [AM335x-PSP 04.06.00.08 Features and Performance Guide](#) provides information on various device driver features and provides performance numbers.

What's Supported

The Linux PSP package supports the following components:

- SPL and U-Boot v2011.09 supporting SPI, NAND, MMC/SD and Ethernet boot modes
- Linux Kernel v3.2 and device drivers
- CCS based NAND flash writers.
- Linux examples.

Linux feature support on EVM (Rev 1.1A and above)

| Peripheral | Instance | Support Status |
|-----------------|----------|---|
| UART | UART0 | Supported. |
| | UART1 | Supported in SDK using Bluetooth module |
| | UART2 | Supported |
| | UART3 | Planned |
| | UART4 | Planned |
| | UART5 | Planned |
| Ethernet Switch | CPSW0 | Supported. IEEE1588 support planned. |
| SPI | SPI0 | Supported |
| | SPI1 | Not available in EVM |
| | I2C0 | Supported |

| | | |
|---------------------|--|--|
| I2C | I2C1 | Supported |
| | | |
| | | |
| | | |
| McASP | McASP0 | Not available in EVM |
| | McASP1 | Supported |
| DCAN | DCAN0 | Not available in EVM |
| | DCAN1 | Supported |
| EDMA | EDMA0 | Supported |
| Timer | Timer0 | Not Tested (Not used in Linux) |
| | Timer1 | Supported (Schedule Tick) |
| | Timer2 | Supported (Clocksource) |
| | Timer3 | Not Tested (Not used in Linux) |
| | Timer4 | Not Tested (Not used in Linux) |
| | Timer5 | Supported (CPSW Interrupt pacing) |
| | Timer6 | Supported (CPSW Interrupt pacing) |
| | Timer7 | Not Tested (Not used in Linux) |
| | Watchdog timer | Supported |
| RTC | RTC0 | Supported |
| ePWM | eHRPWM0 | Not available in EVM |
| | eHRPWM1 | Not available in EVM |
| | eHRPWM2 | Supported (used by Haptics module on EVM) |
| | eQEP0 | Not available in EVM |
| | eQEP1 | Not available in EVM |
| | eQEP2 | Not available in EVM |
| | eCAP0 | Supported in PWM mode (APWM), used as LCD backlight control. Capture mode not supported. |
| | eCAP1 | Not available in EVM |
| | eCAP2 | Not available in EVM |
| Touchscreen/ADC | TSCADC0 | Touchscreen supported, Raw ADC not supported. |
| MMC/SD | MMC/SD0 | Supported |
| | MMC/SD1 | Supported (Profile 2) |
| | MMC/SD2 | Not available in EVM |
| GPIO | GPIO0 | Supported |
| | GPIO1 | Supported |
| | GPIO2 | Supported |
| | GPIO3 | Tested using WLAN/Bluetooth in SDK |
| USB | USB0 | Supported |
| | USB1 | Supported |
| GPMC | GPMC0 | NAND is Supported, NOR is planned. |
| LCD Controller | LCDC0 | GLCD is supported, Character LCD is not supported in EVM |
| Power Management | CPU Idling | Planned (only ARM WFI supported currently) |
| | Dynamic Voltage and Frequency Scaling (DVFS) | Supported |
| | DeepSleep0 | Supported (Suspend-to-RAM) |
| On-board components | Accelerometer | Supported |
| | Ambient Light Sensor | Supported |
| | Temperature Sensor | Supported |
| | Haptics | Supported |

| | | |
|--|-------------|-----------|
| | GPIO keypad | Supported |
|--|-------------|-----------|

Linux support feature support on BeagleBone (Rev A3 and above)

| Peripheral | Support Status |
|------------------|---------------------|
| UART0 | Supported. |
| Ethernet Switch | Supported. |
| MMC/SD0 | Supported. |
| USB0 | Supported. |
| USB1 | Supported. |
| Power Management | Supported as in EVM |

Linux support feature support on EVM-SK (Rev 1.2B and above)

| Peripheral | Support Status |
|------------------------------|---------------------|
| UART0 | Supported. |
| LCD | Supported. |
| Touchscreen | Supported. |
| McASP (audio) | Supported. |
| Ethernet Switch (both ports) | Supported |
| MMC/SD0 | Supported. |
| USB0 | Supported. |
| USB1 | Supported. |
| Power Management | Supported as in EVM |
| Accelerometer | Supported. |
| GPIO-keypad | Supported. |
| GPIO-LED | Supported. |

The PSP package also includes:

- Pre-built binaries for U-Boot, Linux kernel, flash writers and examples
- Relevant Documents

New in this Release

- Support for EVM-SK (Rev 1.2B and later)
- Ethernet Switch
 - Support for two external ports as independent network interfaces
 - Support for VLAN and ALE entry configuration interface
- Suspend-to-RAM (DeepSleep0) with DDR3 support
- DDR3 support in U-Boot
- Support for SPI and Ethernet boot modes in U-Boot

Fixed in this Release

This section lists issues fixed in this release:



ALSA

| Issue Identifier | Issue Headline |
|---------------------------------|---|
| SDOCM00089719 📄 | ALSA: loopback fails when driver is built as module |



Base Port

| Issue Identifier | Issue Headline |
|---------------------------------|--|
| SDOCM00091114 📄 | BasePort: Pin Mux: debugfs shows wrong values |
| SDOCM00091865 📄 | BasePort: Interrupts in bank 4 are not handled |









Ethernet

| Issue Identifier | Issue Headline |
|---|---|
| SDOCM00086213  | Ethernet: "#ethtool eth0" is not showing complete information of Ethernet device |
| SDOCM00091636  | Ethernet: CPSW: must turn off the AM335x internal delay feature on transmit clock |



MMC/SD

| Issue Identifier | Issue Headline |
|---|---|
| SDOCM00085920  | MMC/SD: Beaglebone: multiple times of insert and remove mmc modules with R/W operation causes dut to hang |
| SDOCM00092044  | MMC/SD: HSPE bit needs to be set when MMC/SD clock is above 25MHz |








Power Management

| Issue Identifier | Issue Headline |
|---|---|
| SDOCM00091540  | Power Management: BeagleBone: cpufreq should not set frequencies greater than 500MHz when device is powered using USB |
| SDOCM00090692  | Power Management: I/O error observed when copy files from one USB drive to another USB driver along with suspend resume operation. |
| SDOCM00090696  | Power Management: "LCDC sync lost" and "Kernel core reported suspend failure" messages appear when MMC/SD to MMC/SD file copy along with suspend resume operation |
| SDOCM00090962  | Power Management: Resume operation fails on some beaglebone boards (~1/3 of boards tested) |
| SDOCM00091029  | Power Management: USB: Resume operation take 90 seconds if connected USB device is removed during suspend operation |
| SDOCM00091208  | Power Management: shut down TSC/ADC during suspend if TSC wake is not required |
| SDOCM00092110  | Power Management: 'pll_lock' macro does not correctly wait for PLL lock to happen |
| SDOCM00093513  | Power Management: Fix erratum 1.0.15: OPP50 on MPU domain is not supported |

U-Boot

| Issue Identifier | Issue Headline |
|---|--|
| SDOCM00089686  | U-Boot: EVM: fails when profile 2 is selected to boot using mmc1 |
| SDOCM00092035  | U-Boot: boot fails on using uEnv.txt for setting environment variables |


USB

| Issue Identifier | Issue Headline |
|---|---|
| SDOCM00088841  | USB: Video capture : USB video capture is not working for 640x480 resolution and exit with the message "select timeout" |
| SDOCM00089422  | USB: Wifi driver can not be initialized on AM335x EVM (works on BBB) |
| SDOCM00090435  | USB: using USB2Ethernet interface leads to kernel oops |
| SDOCM00090439  | USB: while transfer big file from EVM to laptop through Atheros wifi dongle a kernel oops occurs |
| SDOCM00090690  | USB: audio: Corrupted audio heard after pause |
| SDOCM00091275  | USB: audio: kernel crashes when attempting to remove mass storage gadget |
| SDOCM00093764  | USB: kernel panic when proc_read() is done after removing g_ether module |

Known Issues

This section lists known issues in this release.

Audio

| Issue Identifier | Issue Headline | Known Workaround(s) |
|---|---|--------------------------------------|
| SDOCM00086121  | AI SA: Audio loopback prints error messages | The warnings are harmless and can be |

| | | |
|---------------|---|----------|
| SDOCM00000422 | ALSA: arecord: Unable to capture audio at exact 24KHz sample rate | ignored. |
| SDOCM00089663 | SD card removal results in noise during ALSA playback/loopback | None |
| SDOCM00088830 | ALSA: arecord: Unable to capture audio at exact 24KHz sample rate | None |

Base Port

This section notes issues with U-Boot and basic kernel board support.

| Issue Identifier | Issue Headline | Known Workaround(s) |
|------------------|--|---|
| SDOCM00085443 | WDT1 timeout inaccurate. | None |
| SDOCM00086716 | HWMOD warnings upon doing WDT file operations | The warning is harmless and can be ignored. |
| SDOCM00085737 | After soft reboot, dhcp or tftp sometimes timeout in U-Boot. | Power cycle the board (hard reboot). |

Ethernet

| Issue Identifier | Issue Headline | Known Workaround(s) |
|------------------|--|---|
| SDOCM00086066 | Ethernet: MAC address configuration is not supported in kernel | None |
| SDOCM00086717 | EVM: NFS: arecord takes longer than expected time to record file to NFS filesystem | None |
| SDOCM00085982 | Beaglebone: UDP client performance at 100Mbps and the throughput is less than 1 Mbps | UDP performance drops suddenly after 95Mbps. UDP rate needs to be throttled to 95Mbps for better performance. |
| SDOCM00091328 | Ethernet: Performance drops to half with file storage IO in progress | None |
| SDOCM00090654 | Ethernet: kernel crashes if removing ethernet module without bringing down network interface | Bring down the network interface before removing ethernet module |

I2C



| Issue Identifier | Issue Headline | Known Workaround(s) |
|------------------|---|--|
| SDOCM00087207 | I2C controller timeout for some slave devices connected on i2c1 at 400KHz | Operating at 100Khz does not cause these timeouts. |

MMC/SD


| Issue Identifier | Issue Headline | Known Workaround(s) |
|------------------|---|---|
| SDOCM00085738 | mmc sd write performance is very low when card is mounted as sync. | It is highly recommended to use async mode for good MMC/SD performance |
| SDOCM00085770 | MMC 8bit is not supported. | None |
| SDOCM00087204 | EVM: write protection for mmc1 in daughter board doesn't work | None |
| SDOCM00089663 | SD card removal results in noise during ALSA playback/loopback | None |
| SDOCM00090498 | MMC: hsmmc driver doesnt support 1.8v MMC cards | None |
| SDOCM00090756 | MMC1: One SD card could not be used as rootfs when in slot1; The same card works in slot0 | This issue happens with one card at the moment and needs further debug. |
| SDOCM00090970 | MMC1 in profile 2: some SD or MMC cards cause DUT to hang | None |

NAND











| Issue Identifier | Issue Headline | Known Workaround(s) |
|------------------|----------------|---------------------|
|------------------|----------------|---------------------|

| Issue Identifier | Issue Headline | Known Workaround(s) |
|---|--|---------------------|
| SDOCM00086033  | Nand mtdtest oob test and subpage test fail. | None |
| SDOCM00090530  | Nand performance in this release is lower than the previous (04.06.00.06) release. | None |


On-board Components

| Issue Identifier | Issue Headline | Known Workaround(s) |
|---|---|---------------------------------------|
| SDOCM00091115  | AM335X: HAPTICS doesn't work on all board revisions | update CPLD to version 1.0E or later. |


Power Management

| Issue Identifier | Issue Headline | Known Workaround(s) |
|--|--|---|
| SDOCM00087097  | cpu_idle reports wrong power consumption numbers for WFI and DDR SR states | None |
| SDOCM00089584  | cpufreq: Unable to change OPP in AM335x evm | This issue is because of misbehavior of I2C client contained inside the CPLD on the EVM. BeagleBone can be used to test CPUFreq on AM335x. BeagleBone does not have a CPLD and does not suffer from the same limitation as the EVM. |
| SDOCM00090470  | Suspend/Resume during MMC/SD write using dd with large block size write causes the file write to not complete | Please use "sync" command before suspending to avoid losing data. Also, please use small block size (eg 512/1024 bytes) for transfer if there is chance of system going to suspend while transfer is going on. |
| SDOCM00090946  , SDOCM00094203  | Suspend: Sometimes (~25 times out of 1000), DUT might abort the suspend process and come back safely to prompt | When this happens, user space can and should retry the suspend operation. |
| SDOCM00090689  | AM335x: USB: aplay/arecord exit with error if system is suspended while playback/recording is ongoing | This issue is because of limitation of USB audio stack in Linux and can be observed on a PC too. Please wait for USB audio to finish before suspending or alternately, retry the audio operation after resume completes. |
| SDOCM00091071  | AM335x: Suspend-to-RAM does not reduce core voltage | None. |
| SDOCM00091498  | AM335x: cpuidle C2 state is not entered | None. |
| SDOCM00091330  | AM335x: i2cdetect throw timeout errors and after that dut hangs after soft reboot | On the EVMs where this issues comes up, i2c usage in suspend-resume via cpufreq should be avoided by disabling cpufreq in the kernel. |
| SDOCM00094261  | AM335x [USB] System does not wake up on inserting USB devices in Suspend state. | None. Using other wakeup modes is recommended. |

SPI

| Issue Identifier | Issue Headline | Known Workaround(s) |
|---|---|--|
| SDOCM00094016  | SPI: SPI_IOC_MESSAGE or read hangs when data read byte is above 158 and bits per words is 16. | For any SPI transfer > 160 bytes, select 8 bits-per-word mode. |

UART

| Issue Identifier | Issue Headline | Known Workaround(s) |
|---|--|---|
| SDOCM00085586  | UART: hardware flow control is not working | This is an issue because of mis-configuration of CPLD present on EVM. The UART driver is expected to work correctly with flow-control. Bluetooth module on EVM used UART flow control successfully. |

USB

| Issue Identifier | Issue Headline | Known Workaround(s) |
|------------------|----------------|---------------------|
|------------------|----------------|---------------------|

| | | |
|--|---|---|
| SDOCM00085670 📄 | USB: NFS stops working when CDC/RNDIS gadget module is inserted with Arago FS | None. This is being tracked as a filesystem issue. http://arago-project.org/cgi-bin/bugzilla3/show_bug.cgi?id=11 📄 |
| SDOCM00085673 📄 | USB File storage gadget: instability when pendrive connected to host port exposed as storage media from gadget port to PC | None |
| SDOCM00087173 📄 | USB: MassStorageGadget: Issues when MMC card is used as storage media or gadget port | None |
| SDOCM00087229 📄 | USB: PIO mode read performance numbers are almost 50% less as compared to that of DMA mode read performance | Use DMA mode of operation if performance is critical. There are some outstanding issues with DMA mode, please go through the rest of this table for information regarding them. |
| SDOCM00089374 📄 | USB: High cpu loading with CDC gadget when connected to another EVM or local loopback | None |
| SDOCM00089782 📄 | USB command verifier (CV) test fails | None |
| SDOCM00091464 📄 | USB: UVC: The UVC camera does not capture the frames after several times of camera turned off and on | None |
| SDOCM00087342 📄 , SDOCM00089599 📄 | USB: CPPI4.1 DMA locks up when CPU mode transfer is done in parallel to DMA transfer. Sometimes USB resets are seen. | Use PIO mode when there is possibility of control transfer in parallel to DMA transfers. Such as when using WiFi and mass storage together or when connecting and disconnecting devices connected to a hub port when DMA transfers are active on another port. Please refer to USB User's Guide for detail on how to enable PIO mode. |

Installation and Usage

Please look for detailed installation and usage instructions in the [AM335x PSP User's Guide](#)

Upgrade and Compatibility Information

There are no known incompatibilities from previous release.

Technical Support and Product Updates

For further information or to report any problems, contact <http://community.ti.com> 📄 or <http://support.ti.com> 📄.

OMAP Linux Mailing List: <http://vger.kernel.org/vger-lists.html#linux-omap> 📄



Engage in the
TI E2E Community
Ask questions, share knowledge, explore ideas
and help solve problems with fellow engineers

For technical support please
post your questions at
<http://e2e.ti.com> 📄. Please post
only comments about the article
AM335x-PSP 04.06.00.08
Release Notes here.

Links



ARM
Microcontroller
MCU 📄

ARM
Processor 📄

Digital
Media
Processor 📄

Digital Signal
Processing 📄

Microcontroller
MCU 📄

Multi Core
Processor 📄

Ultra Low Power
DSP 📄

8 bit Microcontroller
MCU 📄

16 bit Microcontroller
MCU 📄

32 bit Microcontroller
MCU 📄

Categories: [AM335x](#) | [AM35x](#) | [AM37x](#) | [AM1x](#) | [AM18x](#) | [Linux](#) | [PSP](#)

[Leave a Comment](#)

This page was last modified on 1 August 2012, at 18:38.

This page has been accessed 159 times.

Content is available under [Creative Commons Attribution-Share Alike 3.0 license](#).

[Privacy policy](#) [About Texas Instruments Embedded Processors Wiki](#) [Disclaimers](#)

